	CORNER RECORD Document Number 027 · 131 · 06
	City of MILL Valley County of Marin , California
	Brief Legal Description Lands of BICKNETT Massa (formerly Millsap) Per 2005 Maps 18
	CORNER TYPE Government Corner Control
. 3	Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐
XXXX	Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: REESTABLISH THE POUNCLARIES OF THE LANDS OF MILLSAP (NOW)
5	Bicknell & Massa) as identified on 2005 Maps 1800 done by this
7	office. Boundary retraced from found points of said map.
PETALUMA	Misc. Line Points set at random intervals along let lines
0	e reestablish lot corners. See reverse side for locations.
Ÿ	A description of the physical condition of the monument as found and as set or reset: Set either A description of the physical condition of the monument as found and as set or reset:
00	a 1/2" repar with plastic yellow cap stamped "scramor,
2	to surrounding grade) or set brass nail with Brass tag
/ex	stamped PLS 5379. See reverse side for specific locations.
SURVEYIN	SURVEYOR'S STATEMENT
17.	This Corner Record was prepared by me or under my direction in conformance with
5.0	the Land Sulveyor's Act on USUST 25 - ZOIO . No. 5379
97	Signed 1000 91 P.L.S or R.C.E. No. PLS 5379 6-30-2012
五文	OF CAUFOR
Ř,	COUNTY SURVEYOR'S STATEMENT
Š	This Corner Record was received AUGUST 30, 2010
\vec{z}	and examined and filed SEPTEMBER 21, 2010
77	Signed P.L.S. er R.C.E. No. 7128
	Title COUNTY SURVEYOR
	County Surveyor's Comment

Page 1 of 2

Borpels-1297
JU 11023

