


CORNER RECORD

Document Number 027-172-05

City of MILL VALLEY

County of MARIN, California

Brief Legal Description APN: 027-172-05 AS SHOWN PER 2000 MAPS 190



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 4-28-14

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

AS SHOWN ON SHEET 2.

NOTE: THE RECORD POSITION FOR THE 1/2 REBAR + CAP "LS 5065" FALLS IN AN AREA OF RECENT CONSTRUCTION ACTIVITY AND WAS LIKELY DESTROYED. A 1/2 REBAR + CAP "LS 4402" WAS FOUND NEARBY AND IS NOTED ON PAGE 2.

A description of the physical condition of the monument as found and as set or reset:

AS SHOWN ON SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 7-9-14

Signed [Signature] P.L.S or R.C.E. No. P.L.S 8649



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 07-07-2014

and examined and filed July 22, 2014

Signed [Signature] P.L.S or R.C.E. No. 7821

Title DEPUTY



County Surveyor's Comment _____

