CORNER REC	:ORD	9	4 D N 007 07	
City of MILL VALLE	Υ	Document number	A.P.N. 027-23	
		County of MARIN	110011 00 00	, California
Brief Legal Description	NORTHWEST CORNER OF MARIN COUNTY RECORD	S LUI 54 AS SHOWN	UPON 99 O.S.	35,
CORNER TYPE		PE	COORDINATES	
+-	Government Corner	Control 🔲	N	
	Meander Rancho	Property 🛛	E Datum	
	Date of Survey	Other 🗌	Zone Do	
	_			
Corner— Left as	found found and tagge	ed 🗌 Established 🛛	Reestablished 🗌	Rebuilt 🔲
O HEIZED MONUMEN	f corner found: Evidence used to NTS AS SHOWN UPON 99 E NORTHWEST CORNER O	0.S. 35 AS A BASIS	OF BEARINGS	•
		· ·		-
A description of the phy	sical condition of the monume	ent as found and as set o	or reset	
MONUMENTS WERE	UNDISTURBED AND MEAS	SURED PER 99 O.S. ;	35	
SET MONUMENT IS	1/2" REBAR WITH PLAS	TIC CAP, PLS 7744		
			••	
,	SURVEYOR'S STATEMENT	<i>y</i>		
This Corner Record was I	prepared by me or under my	direction in conformance v	with	
the Land Surveyor's Act		2005.	SED	LAND SURV
Signed Im of			[[\$]	EROME
Signed / VIN VV	1 Ml un L.S. Number _	7744		No. 7744
	201 HITY OUR VENEZA		STE EXP	20 7/ NO D
	COUNTY SURVEYOR'S STATEMEN			12.21.01
This Corner Record was r	eceived MARCH 22	20 <u>06</u> and examin	ed Pri	- Strik
and filed APRIL 2	.S, 20 <u>06</u>			CALIFO
Signed		THE COUNTY COUNTY		a Ma
0.19,100	$\overline{}$	Title COUNTY SURVE	702	D LAND SUA
County Surveyor's Comm	mont			
July Julyeyol & Com	HEHL			3/9
			1	хр <u>12-31-06</u> / ф
				No. 7128
				CA CALL

()

