


# CORNER RECORD

Document Number A.P. # 27-237-08

City of Mill Valley County of Marin, California

Brief Legal Description Assessor's Parcel # 27-237-08



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 1/2" Rebars LS 4694 on Easterly Lines.


A description of the physical condition of the monument as found and as set or reset:

Set 1/2 Rebars LS 5290

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on June 6 19 96.

Signed David Harp L.S. or R.C.E. Number LS 5290



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 6-18 19 96 and examined and filed 6-19 19 96.

Signed [Signature] Title DCS



County Surveyor's Comment \_\_\_\_\_

